



<b>DART AEROSPACE LTD</b>	<b>Work Order:</b> 23506
<b>Description:</b> Custom W/O to correct angle	<b>Part Number:</b> D3379-041/-043
<b>Dwg:</b> D3379 Rev. C page 1 & 3	
<b>Ref:</b> N/A	Page 1 of 1

Step	Location	Procedure	By	Date	Qty												
1	DC	Issue Traveler	JS	05.06.03	19												
2	ST	Remove D3379-041 Arm Weldment & D3379-043 Lever Assembly from store. <table><tr><th>Qty</th><th>Part Number</th><th>Description</th><th>Batch</th></tr><tr><td>13</td><td>D3379-041</td><td>Arm Weldment</td><td>B22468A</td></tr><tr><td>6</td><td>D3379-043</td><td>Lever Assembly</td><td>B22624 &amp; B22468A B22470</td></tr></table>	Qty	Part Number	Description	Batch	13	D3379-041	Arm Weldment	B22468A	6	D3379-043	Lever Assembly	B22624 & B22468A B22470	CPL	06/11/30	19
Qty	Part Number	Description	Batch														
13	D3379-041	Arm Weldment	B22468A														
6	D3379-043	Lever Assembly	B22624 & B22468A B22470														
3	MFA	Rework by correcting the angle as per Dwg D3379	CPL	06/11/30	19												
4	QC5	Inspect work to Step 3.	NA	06/11/30	19												
6	FP	If necessary Powder Coat Fire Red (Ref. 4.3.5.10) as per QSI 005 4.3 or touch with paint D3379-041	Y/L	06/12/06	x19												
7	QC3	Inspect Powder Coat or paint	FC	06/12/07	19												
8	ST	Identify and Stock D3379-041 & D3379-043 as per step 2	CPL	06/12/07	19												
9	AC	Charge to project number P601-571/-572 Cost / part: _____															
10	DC	Close W/O Inspect Level 21	LD	06/12/22	19												
(Note: Attach a copy of Custom W/O to each of the W/O's listed in Step 2 above)																	

(Note: Attach a copy of Custom W/O to each of the W/O's listed in Step 2 above)

Rev	Date	Change	Revised By	Approved
A	05.06.02	New Issue	KJ/RF	

Qty	P/N	Description	Batch	By	Date	Qty
14	D3379-1	Support	B22817 B22471 B22626	CPL	06/11/29	19




**NOTES:**

- 1) MATERIAL: 1018-1025 ROUND TUBING MILD STEEL SEAMLESS (REF. DART SPEC. M1018TR1.250W.109)
- 2) WELD PER QSI 004
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE INCHES
- 5) BREAK ALL SHARP EDGES 0.005 TO 0.010

DESIGN	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
CHECKED	APPROVED	DRAWING NO. D3379
DATE 05.05.27	TITLE ARM WELDMENT	REV. 1 SHEET 3 OF 4 SCALE 1:3

DESIGN <i>[Signature]</i>	DRAWN BY <i>[Signature]</i>	<b>DART AEROSPACE LTD</b> HAWKESBURY, ONTARIO, CANADA	
CHECKED	APPROVED	DRAWING NO. D3379	REV. C SHEET 1 OF 4
DATE 05.05.27		TITLE ARM WELDMENT	SCALE 1:1
A	04.12.13	NEW ISSUE	
B	05.02.25	RE-DESIGN D3379-5	
C	05.05.27	2" WAS 4"	



### D3379-041 ARM WELDMENT

#### NOTES:

- 1) POSITION PARTS AS PER JIG D3379-041T1
- 2) WELD PER DART QSI 004
- 3) FINISH: POWDER COAT FIRE RED (REF 4.3.5.10) PER DART QSI 005 4.3
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 5) ALL DIMENSIONS ARE IN INCHES
- 6) BREAK ALL SHARP EDGES 0.005 TO 0.010

**PRELIMINARY ISSUE**

Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Work Order:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Manuf / Design Mgr	Approval QC Inspector

NCR		WORK ORDER NON-CONFORMANCE						
DATE	STEP	Description of NC section A	Corrective Action Section B	Sign & Date	Verification Section C	Approval Design Mgr	Approval QC Inspector	
05.06.22	7	Quarantine - will be reworked at a later date per RF 73373-041	Initial u	Quarantine rework after confirmation from test plan. 05.06.22				

PAR#: \_\_\_\_\_ Fault Category: \_\_\_\_\_ DQA: \_\_\_\_\_ Date: \_\_\_\_\_